# SPT011 HOC - ASSEMBLY INSTRUCTIONS

Contents

1 x set of
Cores

1 x Portrait Header

2 x Wire Base Supports

**Push in tabs**

1 Expand header and push in tabs.

2 Assemble wire support as shown above.

a

b

3 a) Join cores together by inserting spigot of bottom core into the top.
b) Insert pole through top hole and onto bottom middle points.

4 Lower made up header onto core settling the header on the core.

5 The unit is now complete.